

Blade Shop

AIRBUS PRODUCTS MAIN ROTOR BLADES AS332


L/L1 Replacement of all, or individual leading edges due to separation/cracks or wear. Static balancing. Trim tab repair or replacement. PU spacing rings replacement. Paint touch-up. Modification from 332A11-0024 to 332A11-0025, and lower surface polyurethane protection replacement.

L2 Replacement of all, or individual leading edges due to separation/cracks or wear. Static balancing. Trim tab repair or replacement. PU spacing rings replacement. Paint touch-up. Lower surface polyurethane protection replacement.


H225 Leading edge tip cap replacement, trim tab repair or replacement and lower surface polyurethane protection replacement. Repair of PU spacing rings.

SIKORSKY S92 MAIN ROTOR BLADES

- Erosion nickel strip replacement
- Minor skin repairs
- Paint touch-up
- Wire mesh repair




Blade stripped for SS-strips for replacement MK-1



Replacement of SS-strip on leading edge MK-2



Before repair S92



After repair

To always keep you safe and mission-ready while reducing cost of ownership

CONTACT
sales@heli-one.ca

www.heli-one.ca

A division of CHC Helicopter

See full list of what we can do for you at www.heli-one.ca/about-us/facilities/stavanger-norway



Heli-One
Excellence in Helicopter
Maintenance Services