

AS350 BLADE REPAIR

THE BLADE SHOP IS LOCATED NEAR THE MAIN MRO FACILITY AND FEATURES CUSTOM SPACE FOR IMPROVED EFFICIENCY AND SPECIAL PROCESSES.

Heli-One Norway repairs Airbus AS350/355 rotor blades with an estimated 10 day turnaround time. Their state-of-the-art Blade Shop has specialized tooling and resources that facilitates quick repair work. The shop is qualified for COV (Level I+) and BOV (Level D) work. Technicians were trained by the OEM to perform repair work.



MAIN BLADE MRO SERVICES



THE SHOP ALSO FEATURES A SPECIAL PROCESSES CLEAN ROOM

PART NUMBER

DESCRIPTION

SCOPE

350A11-0020-xx

350A11-0030-xx

Main Rotor Blades

Nickel strip replacement
Trim tab repair and replacement
Paint
Skin damage repair
Repair of trailing edge damages
Repair of bonding fail
Static balancing
Lower surface polyurethane repair and replacement

TO ALWAYS KEEP YOU SAFE AND MISSION-READY
WHILE REDUCING COST OF OWNERSHIP

CONTACT US

sales@heli-one.com

www.heli-one.com

Heli-One
Excellence in Helicopter
Maintenance Services