

AW169 FLOATS & RAFTS

Heli-One's Rescue Equipment workshop continues to gain capabilities to reflect the global fleet and market demands. This unique workshop has recently added repair and overhaul capability for the Leonardo AW169 floats and rafts.



A TECHNICIAN INSPECTS A PAIR OF FLOATS IN THE WORKSHOP.

HIGHLIGHTS:

- Service interval for rafts and floats is 30 months
- Target turnaround time for service is 30 days
- Typical scope of work: floats are inspected, rafts are overhauled, raft cylinders are also hydrostatic tested
- The Stavanger Rescue Equipment workshop is staffed with experienced and specialized technicians that work on rescue equipment for various aircraft types.
- The workshop is equipped with the latest maintenance and testing equipment ensuring that your equipment is being serviced under strict quality standards.

AW169 CAPABILITIES

Heli-One has developed an EMS-focused cabin modification for the AW169 including a modular medical wall and stretcher solution that meets patient transport requirements. Contact our team for more information.

PART NUMBERS

- 6F9560V00131 - FWD L/H
- 6F9560V00231 - FWD R/H
- 6F9560V00331 - AFT L/H
- 6F9560V00431 - AFT R/H

TO ALWAYS KEEP YOU SAFE AND MISSION-READY
WHILE REDUCING COST OF OWNERSHIP

CONTACT US sales@heli-one.com www.heli-one.com

Heli-One
Excellence in Helicopter
Maintenance Services