

Engine Accessory Catalogue

Heli-One 
Excellence in Helicopter
Maintenance Services



2017 PRICING

HELI-ONE CANADA

PT6C-67C

PT6T

CT58/T58



Heli-One Engine Accessory Shop

Heli-One Canada's Engine Accessory Shop is a dedicated workshop for the testing, repair, and overhaul of various General Electric and Pratt & Whitney engine components. We are an authorized engine accessory service facility with decades of experience in these engine types. Our dedicated workshop is equipped with a wealth of specialized resources and tools that enable us to keep turnaround times and costs low.

Supported Platforms:

Pratt & Whitney PT6C-67C

Pratt & Whitney PT6T

General Electric T58/CT58



Pratt & Whitney PT6C-67C Series Engine

Category	Description	Part Number	Capability	Price	TAT
Fuel System	Fuel Nozzle (Qty 14)	3073974-01	Cleaning & Functional Test (300/600HR)	\$168 (each nozzle)	10 Days
		3073976-01		\$2,360 (set)	
		3058617-01	Basic Overhaul	\$5,880	50 Days (Set)
		3058932-01			
		3059126-01	Average Overhaul	\$6,880	
			Basic Exchange	\$6,880	-














BASIC OVERHAUL PRICING INCLUDES FUNCTIONAL TEST, PMA PARTS, BASIC LABOUR AND BASIC BOM KITS
AVERAGE OVERHAUL PRICING WITH PMA PARTS INCLUDES BASIC LABOUR AND BASIC BOM KITS
BASIC EXCHANGE PRICING WITH PMA PARTS EXCLUDES OVER AND ABOVE PARTS, REWORKS & REPAIRS

PRICING IS SUBJECT TO CHANGE WITHOUT NOTICE. PRICING IN US\$. PLEASE CONTACT US FOR THE MOST UPDATED PRICING. O&A PARTS REQUIREMENTS OR REWORKS ARE DETERMINED AT QUOTE SUBMISSION. TAT REFERS TO TURNAROUND TIME IN WORK DAYS AND IS SUBJECT TO OEM PART DELAYS.

Pratt & Whitney PT6T Series Engine

Category	Description	Part Number	Capability	Price	TAT		
Air System	P3 Filter Element	3038142	Overhaul	\$380	7 Days		
		3118494-01 3059788-01 3059787-01	Basic Exchange	\$430	-		
Fuel System	PT6T-3D Fuel Manifold Set (Qty 14)	3039638	Clean & Functional Test (600HR)	\$950	15 Days		
		3039638RE03	Basic Overhaul	\$2,560	20 Days		
		3054522-01					
		3039637	Average Overhaul	\$2,960			
		3039637RE03					
		3054520-01					
		Basic Exchange	\$3,060	-			
	PT6T-3B Fuel Manifold Set (Qty 14)		Clean & Functional Test (600HR)	\$670	15 Days		
		3019536	Basic Overhaul	\$1,990	20 Days		
		3019537					
		3019426	Average Overhaul	\$2,760			
		Basic Exchange	\$2,490	-			
Lubrication System	Oil Filter	303637	Basic Overhaul	\$380	7 Days		
		3029315	Basic Exchange	\$430	-		
		3034508					
		3059256-01					

General Electric T58/CT58 Engine Series

Category	Description	Part Number	Capability	Price	TAT	
Lubrication System	#1 Oil Nozzle	6029T27G03	Functional Test	\$190	5 Days	
	#2 Oil Nozzle	6029T69P01	Functional Test	\$190	5 Days	
	PT Oil Nozzle	5004T67P10	Functional Test	\$190	5 Days	
Fuel System	Fuel Manifold (half)	4002T23G05 4002T23G06 4002T23G11 4002T23G12	Functional Test	\$480	7 Days	
			Basic Overhaul	\$2,160	20 Days	
			Average Overhaul	\$4,420		
			Basic Exchange	\$2,660	-	
Engine	T5 Harness	5003T78P02 5003T78P04	Functional Test	\$480	3 Days	

BASIC OVERHAUL PRICING INCLUDES FUNCTIONAL TEST, PMA PARTS, BASIC LABOUR AND BASIC BOM KITS
AVERAGE OVERHAUL PRICING WITH PMA PARTS INCLUDES BASIC LABOUR AND BASIC BOM KITS
BASIC EXCHANGE PRICING WITH PMA PARTS EXCLUDES OVER AND ABOVE PARTS, REWORKS & REPAIRS

PRICING IS SUBJECT TO CHANGE WITHOUT NOTICE. PRICING IN US\$. PLEASE CONTACT US FOR THE MOST UPDATED PRICING. O&A PARTS REQUIREMENTS OR REWORKS ARE DETERMINED AT QUOTE SUBMISSION. TAT REFERS TO TURNAROUND TIME IN WORK DAYS AND IS SUBJECT TO OEM PART DELAYS.

General Electric T58/CT58 Engine Series

Category	Description	Part Number	Capability	Price	TAT	
Air System	Anti-Ice Valve		Functional Test	\$290	5 Days	
		3006T97P01	Basic Overhaul	\$1,930	10 Days	
		3014T56P01				
		3014T56P02	Average Overhaul	\$3,200		
		4025T87P01				
	4025T87P03		Basic Exchange	\$2,430	-	
	Stator Vane Actuator		Functional Test	\$290	5 Days	
		4004T63G04	Basic Overhaul	\$1,100	10 Days	
		4004T63G05				
		4004T63G07	Average Overhaul	\$3,440		
		4004T63G10				
		Basic Exchange	\$1,600	-		
	Bleed Valve		Functional Test	\$290	5 Days	
		4003T62P01	Basic Overhaul	\$2,450	10 Days	
		4003T62P03				
4003T62P04		Average Overhaul	\$6,240			
4003T62P05						
	Basic Exchange	\$2,950	-			
Lubrication System	Oil Cooler	37D400478P101 573D264P3	Functional Test	\$380	5 Days	



Excellence in Helicopter
Maintenance Services

FOR MORE INFORMATION CONTACT:

Sales@Heli-One.ca
T +1.844.570.4677

HELI-ONE CANADA

4740 Agar Dr
Richmond, British Columbia
Canada V7B 1A3
T +1 604 952 7700

www.heli-one.com

Part of CHC Helicopters