


GE CT58/T58 Capabilities

Heli-One provides repair and overhaul services for the GE CT58/T58 engine with an average 45 Day TAT. With nearly 90 in-house repairs developed, experienced technicians, and extensive in-house resources, Heli-One can service your engine quickly and efficiently.



BENEFITS:

- Average 45 Day TAT for overhaul (with component exchanges, 60 Day TAT without exchanges)
- Over 90 in-house CT58 repairs developed to reduce cost and save time
- Extensive in-house resources including: testing, accessory shop, welding, cleaning, NDT, and engineering
- Mobile Repair Team available for field service
- 800+ CT58/T58 overhauls completed
- Ready inventory of engines, engine accessories and parts
- Engines available for Exchange and Rent
- 200yrs+ of combined aviation experience in Engine technician team

CT58/T58 MODEL TYPES SERVICED

CT58-140-1
CT58-140-2
T58-10
T58GE10
T58GE100
T58GE402
T58GE8F

HELI-ONE DAR REPAIRS

Heli-One's in-house designed Design Airworthiness Repairs (DAR) meet regulatory standards and prolong the lifespan of parts, which means immediate and long-term cost savings for customers.



Engine Team Has Completed Over
800 Overhauls

To always keep you safe and mission-ready while reducing cost of ownership

CONTACT

sales@heli-one.ca

www.heli-one.ca

A division of CHC Helicopter

See full list of what we can do for you at heli-one.ca/about-us/facilities/vancouver-canada



Heli-One
Excellence in Helicopter
Maintenance Services