

Spectrolab® Searchlights

Heli-One's extensive repair capabilities have proven why it is an industry leader in Helicopter repairs. With our world-class turnaround times we can completely repair searchlight systems in just 10 days. Approved Service center for all Spectrolab® searchlight systems.

QUICK FACTS

AS332/532 MK1/2 and H225/EC725

- 10 days average TAT
- Approved Service center for all Spectrolab® searchlight systems
- Approvals include EASA, TCCA, and ANAC

DESCRIPTION

PART NUMBER

Nightsun XP	033338-xxx 033704 033537
Nightsun SX-16	017500-xxx 025000-xxx
Starburst SX-5	024711-xxx 032500-xxx



SPECTROLAB

A BOEING COMPANY

To always keep you safe and mission-ready while reducing cost of ownership

CONTACT

sales@heli-one.ca

www.heli-one.ca

A division of CHC Helicopter

See full list of what we can do for you at www.heli-one.ca/about-us/facilities/stavanger-norway

Heli-One Norway

Heli-One
Excellence in Helicopter
Maintenance Services